

Date: March 7th, 2018

EOG Canada Oil & Gas Inc 1300- 700- 9th Avenue SW Calgary, AB T2P 3V4

Attention: Zaine Tymrick, VP operations

Re: <u>EOG Canada Oil & Gas Certificate of Restoration Application (part II) for the Well Site ECOG TH Alces A10-16-83-14 W6M (WA # 18569)</u>

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 18569) submitted by Summit liability Solutions Inc. on behalf of EOG Canada Oil & Gas Inc. on January 24th, 2018.

The reclamation assessment report reviewed and found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5845).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore EOG Canada Oil and Gas Inc remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer

Environmental Management & Reclamation Department

Operational Policy & Environment

Telephone: 250-794-5234 Facsimile: 250-794-5380

E-Mail: Taher.Morsi@gov.bc.ca


cc: Caryn Mann, Summit Liability Solutions Inc, Suite 110, 855-42 Avenue SE,

Calgary, AB T2G 1Y8



CERTIFICATION OF RESTORATION **APPLICATION FORM - PART 2**

Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J2B0 Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c.

53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature. **COMMISSION USE ONLY** A Commission File No. or AD No.: Document: **ADMINISTRATION** В Well Permit No.: 18569 Well Name: ECOG TH ALCES A10-16-083-14 Well Location: 10-16-083-14 W6 Petroleum Title (Permit, Lease, Number, etc): AD No. 100044466 Title Holder(s) (Permittee, Lessee, etc): EOG Canada Oil and Gas Inc. Surface Landowner: Robert Vander Linden, Morley and Linda Surface Occupant: Not applicable Bradley, Harvey Madill, Larry Vander Linden, and Elvern Esau (Attach Letter of Release) (Attach Letter of Release) Applicant's Agent in Field Name: Caryn Mann Position: Regional Manager - Environmental Assessment Company: Summit Liability Solutions Inc. Services Address: Suite 110, 855 - 42 Avenue SE City: Calgary Province: AB Phone: 403-802-3633 ext. Postal Code: T2G 1Y8 Fax: 403-802-3634 Email: cmann@summitls.ca Agent Signature: \$1500 Application Fee Attached RESTORATION INFORMATION C Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location): A 120 metre (m) by 120 m wellsite, 2395 m access road, and 60 m by 90 m remote sump located at 01-28-083-14 W6 are associated with this site. The wellsite, access road and remote sump are located on private land. The landowner of the wellsite is Robert Vander Linden. The landowners of the access road are Morley and Linda Bradley, Harvey Madill, and Larry Vander Linden, and the landowner of the remote sump is Elvern Esau.

Morley and Linda Bradley and Larry Vander Linden have signed releases for their portion of the pre-existing access road. Harry Madill

has been contacted several times via phone and mail but was not able to be reached and has not signed a release for his portion of the

pre-existing access road. Elvern Esau has signed a release to confirm that the remote sump has been satisfactorily reclaimed.

Updated: 23-June-2016 Effective: 23-June-2016

Reclamation Inspection Report included?

Details of any areas left unrestored at Landowner's request:

Was "Approval to Construct" subject to any reclamation conditions?

 \times NO

XYES

Schedule B		YES NO
SSION USE ONLY		D
CERTIFICATE NO.	5845	
nistry of Environment h uance of this centificate responsible by the Con	as the authority to order fur does not relieve the Applicantission.	ther site
	or incidental to, the above nistry of Environment has uance of this centificate responsible by the Con	SSION USE ONLY

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act.* Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act.* If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.

Updated: 23-June-2016 Effective: 23-June-2016