

Date: January 19th, 2018

TAQA North Ltd
2100, 308-4th Avenue SW
Calgary, AB T2P 0H7

Attention: Wes Bell, Northern Environmental Coordinator

Re: TAQA North Certificate of Restoration Application (Part-II) for the Well Site TAQA North Et Al Chinchaga A-94-I/94-H-1 (WA # 18970)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite the above referenced well authorization (WA # 18970) submitted by TerraLogix Solutions Inc. on behalf of TAQA North Ltd on December 22nd, 2017.

Based upon review of the information provided by the applicant, the reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5756).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore TAQA North Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi', with a long, sweeping underline that extends to the right.

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer
Operational Policy & Environment
Resource Development & Stewardship Branch
Telephone: 250-794-5234
Facsimile: 250-794-5390
E-Mail: Taher.Morsi@bcogc.ca

cc: Jody Stevens, TerraLogix Solutions Inc., #323, 3750- 46 Ave S.E., Calgary, AB
T2B0L1



**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**
Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY

A

Commission File No. or AD No.:

Document:

ADMINISTRATION

B

Well Permit No.: **18970**

Well Name: TAQA NORTH CHINCHAGA A-094-I/094-H-01

Well Location: A-094-I/094-H-01

Petroleum Title (Permit, Lease, Number, etc): 53022

Title Holder(s) (Permittee, Lessee, etc): TAQA North Ltd. (6.52 %) and Signalta Resources Ltd. (93.48%)

Surface Landowner: BC Oil and Gas Commission
(Attach Letter of Release)

Surface Occupant: N/A
(Attach Letter of Release)

Applicant's Agent in Field

Name: Jody Stevens, P.Ag.

Company: Terralogix Solutions Inc.

Position Senior Manager

Address: 323, 3750 46 Ave Se

City: Calgary

Province: Alberta

Postal Code: T2B 0L1

Phone: 403-217-7787

Fax: 403-217-7709

Email: jody.stevens@terralogix.ca

Agent Signature: 

Date: December 11, 2017



\$1500 Application Fee Attached Yes

RESTORATION INFORMATION

C

Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):

The landscape, soils, and vegetation on the wellsite and access road have been reclaimed to the equivalent land capability of the surrounding area and have met the Reclamation Assessment Criteria standards. The proposed log deck on the survey plan was never constructed.

Wellsite: 1.00 ha (100 m x 100 m)

Access Road: 0.11 ha (109 m x 10 m)

Details of any areas left unrestored at Landowner's request:

None.

Was "Approval to Construct" subject to any reclamation conditions?

☐ YES

☒ NO

Reclamation Inspection Report included?

☒ YES

☐ NO

Is this location within the Agricultural Land Reserve? If YES, attach Schedule B

☐ YES

☒ NO

CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5756

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Jan 19th, 2018

Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.