



Date: January 17<sup>th</sup>, 2020

Petronas Energy Canada Ltd  
1600-215- 2<sup>nd</sup> Street SW  
Calgary, AB T2P 1M4

Attention: Carl Lammens, Team Lead, Asset Retirement & Remediation

Re: Petronas Energy Canada Certificate of Restoration Application (Part-II) for the Well Site Petronas W BEG B-67-C/94-G-01 (WA # 19585)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report (**Never Drilled**) for wellsite for the above referenced well authorization (WA # 19585) submitted by Acden Vertex Limited Partnership on behalf of Petronas Energy Canada Ltd on December 23<sup>rd</sup>, 2019.

Based upon review of the information provided by the applicant, the reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 6070).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

**"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."**


And:

**"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."**

Therefore Petronas Energy Canada Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi', written over a horizontal line.

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer  
Resource Development & Stewardship Branch  
Operational Policy & Environment  
Telephone: 250-794-5234  
Facsimile: 250-794-5390  
E-Mail: Taher.Morsi@gov.bc.ca

cc: Steven vanNieuwkerk, Acden Vertex Limited Partnership, 161, 2055 Premier Way, Sherwood Park, AB T8H 0G2

**CERTIFICATION OF RESTORATION APPLICATION FORM - PART 2**  
 Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6  
 Mailing Address: Bag 2, Fort St. John, B.C. V1J 2B0  
 Phone: (250) 794-5209



**RECEIVED**  
 DEC 23 2019  
 Date Received  
 BC Oil and Gas Commission

**THIS IS AN AUDITABLE DOCUMENT**  
 This form must be submitted under the authority of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2009, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

<b>COMMISSION USE ONLY</b>	
<b>A</b>	Commission File No. or AD No.:
<b>B</b>	Document
<b>ADMINISTRATION</b>	
Well Permit No.: 19665	Well Name: PETRONAS W BEG B-067-C/094-G-01
Well Location: B-67-C/94-G-1	Petroleum Title (Permit, Lease, Number, etc.): 9620166
Surface Landowner: Crown	Title Holder(s) (Permittee, Lessee, etc.): PETRONAS Energy Canada Ltd.
Surface Occupant: N/A	Applicant's Agent in Field
(Attach Letter of Release)	Name: Steven vanNieuwenkerk
(Attach Letter of Release)	Company: Acden Verex Limited Partnership
Position: General Manager, Report Review	Address: 161, 2055 Premier Way
Province: Alberta	Postal Code: T8H 0G2
Email: svannieuwenkerk@verex.ca	Phone: 780-464-3285
Date: December 18, 2019	Fax: 780-464-3731
Agent Signature: <i>[Signature]</i>	
<input checked="" type="checkbox"/> \$1500 Application Fee Attached <input type="checkbox"/> P.A.G.	
<b>DESCRIPTION INFORMATION</b>	
<b>C</b>	Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affected with this location):
Wellbore and access road	
Details of any areas left unrestored at Landowner's request:	
N/A	
Was "Approval to Construct" subject to any reclamation conditions?	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
Reclamation Inspection Report included?	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO

CERTIFICATE OF RESTORATION

CERTIFICATE NO.

6070

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Jan 17, 2020



Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.