



Date: February 23rd, 2018

Progress Energy Canada Ltd
1600, 215 – 2nd Street S.W.
Calgary, AB
T2P 1M4

Attention: Carl Lammens, Senior Environmental Specialist

Re: Progress Energy Canada Certificate of Restoration Application (Part-II) for the Well Site Progress Julianne C-71-A/94-G-02 (WA # 20117)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 20117) submitted by Secure Energy Services Inc on behalf of Progress Energy Canada Ltd on January 12th, 2018.

The reclamation assessment report and additional information reviewed and found that the site has fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5824).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Progress Energy Canada Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi', written over a horizontal line.

Taher Morsi, Ph.D., P.Ag
Environmental Management Officer
Telephone: 250-794-5234
Facsimile: 250-794-5380

E-Mail: Taher.Morsi@bcogc.ca

cc: Sherry Stewart Ryan, Secure Energy Services Inc, 120-8832 Blackfoot
Trail SW, Calgary, Albert T2J-3J1


**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**

Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY			A
Commission File No.:		Document:	
ADMINISTRATION			B
Well Permit No.: 20117			
Well Name: PROGRESS JULIENNE C-071-A/094-G-02		Well Location: c-071-A/094-G-02	
Petroleum Title (Permit, Lease, Number, etc): WA# 20117			
Title Holder(s) (Permittee, Lessee, etc): Progress Energy Canada Ltd.			
Surface Landowner: Crown Land <i>(Attach Letter of Release)</i>		Surface Occupant: <i>(Attach Letter of Release)</i>	
Applicant's Agent in Field			
Name: Sherry Stewart Ryan			
Company: SECURE Energy Services Inc.		Position: Project Manager	
Address: 120 – 8832 Blackfoot Trail SW		City: Calgary	Province: Alberta
Postal Code: T2J 3J1	Phone: 403-720-6011	Fax: 403-720-6007	Email: sstewart@secure-energy.com
Agent Signature: 		Date: Nov 29/17	
<input checked="" type="checkbox"/> \$1500 Application Fee Attached			

RESTORATION INFORMATION		C
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):		
Wellsite, access road, decking site		
Details of any areas left unrestored at Landowner's request:		
The remote sump and Decking Site # 1 were not utilized or disturbed.		
The portion of access road from the Alaska Highway has now become the Mile 142 Road up to the a-071-A Pad Site. The next portion of access road up to the Abandoned b-071-A/094-G-02 wellsite has been requested to remain in place by Canfor to access forestry cutblocks in the area that still have silvicultural obligations (see attached).		
Therefore, only the areas outlined in red on the attached survey have been restored and are included in this application.		
Was "Approval to Construct" subject to any reclamation conditions?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Reclamation Inspection Report included?		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

