



Date: March 14th, 2017

Direct Energy Marketing Ltd
Suite 1200- 525 8th Avenue SW
Calgary, AB, T2P1G1

Attention: Jonathan Mast, Remediation Coordinator

Re: Direct Energy Marketing Certificate of Restoration Application (Part-II) for the Well Site Direct HZ Stone B-26-L/93-P-12 (WA # 20815)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 20815) submitted by SNC-Lavalin Environment on behalf of Direct Energy Marketing Ltd on March 8th, 2017

Based upon review of the information provided by the applicant, the reclamation inspection report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5717).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore potential liability related residual contamination from the subject oil and gas activity on site remains the responsibility Direct Energy Marketing Ltd

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi', written over a horizontal line.

Taher Morsi, Ph.D., P.Ag
Environmental Management Officer
Telephone: 250-794-5234
Facsimile: 250-794-5380

E-Mail: Taher.Morsi@bcogc.ca

cc: Kathleen Juneau, SNC-Lavalin Environmental & Water Inc, #202- 10012 97th
Avenue, Fort St John V1J 5P3



**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**
 OGC, 100 10003 110 AVE
 Fort St. John, B.C. V1J 6M7
 Phone: (250) 794-5200

RECEIVED
 MAR 08 2017
 BC Oil and Gas Commission
 Date Received

THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY A

Commission File No.: _____ Document: _____ Application Fee: \$ _____

ADMINISTRATION B

Well Permit No.: 20815	
Well Name: Direct HZ Stone B-026-L/093-P-12	Well Location B-026-L/093-P-12
Petroleum Title (Permit, Lease, Number, etc): OGC File; Not available	
Title Holder(s) (Permittee, Lessee, etc): Direct Energy Marketing Limited	
Surface Landowner: Crown <i>(Attach Letter of Release)</i>	Surface Occupant: N/A <i>(Attach Letter of Release)</i>
Applicant's Agent in Field: SNC-Lavalin	
Name: Jonathan Mast, B.Sc., P.Ag.,	
Company: Direct Energy Marketing Limited	Position: Remediation Coordinator
Address: 1200 - 525 8th Ave SW	City: Calgary
Postal Code: T2P 1G1	Phone: 403 351 9435
Agent Signature: 	Date: 3 March 2017

RESTORATION INFORMATION C

Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):
 This site consists of a lease site, access road, remote DWDA, temporary campsite, and decking site. The site is on crown land and its status is "Abandoned". The site is now suitable for a Certificate of Restoration Part 2 approval.

Details of any areas left unrestored at Landowner's request:

N/A

Was "Approval to Construct" subject to any reclamation conditions? – Nothing found in OGC file.	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Reclamation Inspection Report included?	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO


CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5717

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

March 14th, 2017

Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.