

Date: April 18th, 2018

ARC Resources Ltd Suite 1200-308- 4th Avenue SW Calgary, AB T2P 0H7

Attention: Mark Roblin, Environmental Coordinator

Re: <u>ARC Resources Certificate of Restoration Application (Part-II) for the Well</u> Site ARCRes DOE 03-32-80-14 W6M (WA # 22510)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment (Schedule B) Report for wellsite (<u>Never Drilled</u>) for the above referenced well authorization (WA # 22510) submitted by NewAlta Corporation on behalf of ARC Resources Ltd on April 16th, 2018.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5869).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

T 250.794-5200 F 250.794-5390 www.bcogc.ca

Therefore ARC Resources Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,


Taher Morsi, Ph.D., P.Ag

Environmental Management Officer Resource Development & Stewardship Branch Operational Policy & Environment Telephone: 250-794-5234 Facsimile: 250-794-5390 E-Mail: Taher.Morsi@gov.bc.ca

cc: Blake Bouzek, NewAlta Corporation, 211-11 Avenue SW., Calgary AB, T2R0C6



CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2 Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J 2B0 Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

A

С

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY

					4		
Commission File No.: Document:							
		ADMINI	STRATION		В		
Well Permit No.: 22510							
Well Name: Built Not Drilled			Well Location: 03-3	Well Location: 03-32-080-14 W6M			
Petroleum Title (Permit, Lease, Number, etc):							
Title Holder(s) (Permittee, Lessee, etc): Arc Resources Ltd.							
Surface Landowner: Dorothee Walburga Luise Huenseler			Surface Occupant: I	Surface Occupant: Barry Follensbee			
(Attach Letter of Release)			(Attach Letter of Release)	(Attach Letter of Release)			
Applicant's Agent in Field							
Name: Blake Bouzek, P. Eng.							
Company: Newalta Corporation			Position: Technical	Position: Technical Manager			
Address: 211 - 11 th Ave SW City: Calgary			Province: Alberta				
Postal Code: T2R 0C6	Phone: 403-80	06-7000	Fax: 403-806-7349	Email: BBouzek@newalta.com			
Agent Signature:	Bars			Date: Apr; 1 10, 2018			
4500 Application Eco Attached							

\$1500 Application Fee Attached

RESTORATION INFORMATION

Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):

The Built Not Drilled lease site at 03-32-080-14 W6M has been restored. The wellsite measures130 m x 120 m and has an associated access road .

Details of any areas left unrestored at Landowner's request:

A culvert and approach (measuring 22 m by 5 m adjacent to the road allowance) remain in place. Ms. Huenseler, the landowner, resides in Germany. Multiple attempts to contact the landowner by phone and fax have been made dating back to November 2017; however, to date the landowner has not responded. A signed release for surface facilities remaining in place and acknowledging satisfaction with the reclamation work has not been obtained from Ms. Huenseler. The occupant has signed off for the facilities to remain in place.

Attempts to contact Ms. Huenseler include:

- November 15, 2017 Phone call, left voicemail with the landowner
- November 24, 2017 Phone call, left voicemail with the landowner
- December 11, 2017 Faxed surface release and reclamation release documents to landowner
- December 11, 2017 Phone call, left voicemail with the landowner
- December 13, 2017 Phone call, left voicemail with the landowner
- January 8, 2018 Phone call, left voicemail with the landowner

Was "Approval to Construct" subject to any reclamation conditions?

Reclamation Inspection Report included?

YES

XYES

MNO

NO

Is this location within the Agricultural Land Reserve? If YES, attac					
APPROVAL – FOR COMMISSION USE ONLY D					
CERTIFICATE OF RESTORATION	CERTIFICATE NO.	5869			
This is to certify that the surface of the land held in conjunction with, satisfactorily restored. Despite the issuance of this Certificate, the M investigation or remedial action upon inspection of the site or file. Is restoration requirements for which the Applicant is subsequently held Approval Date: $Apri \left(18^{H} - 2318 \right)$	linistry of Environment has suance of this certificate do	the authority to order further site bes not relieve the Applicant of any ission.			
The personal information requested on this form is collected under the author Natural Gas Act and the Environmental Management Act. Under certain circu the Freedom of Information and Protection of Privacy Act. If you have any qui the Corporate Services Branch, Records Administrator, in Fort St. John at the	mstances, some information r estions about the collection, us	nay be released subject to the provisions of			