

Date: February 16th, 2018

Canadian Natural Resources Ltd Suite 2500, 855- 2nd Street SW Calgary, AB T2P 4J8

Attention: Ryan Okada, Lead Reclamation

Re: <u>Canadian Natural Resources Certificate of Restoration Application (part II) for the</u> Well Site CNRL Kahntah B-16-F/94-H-15 (WA # 22520)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 22520) submitted by SynergyAspen Environmental on behalf of Canadian Natural Resources Limited on January 2nd 2018.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5797).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:


"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Canadian Natural Resources Limited remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234



Taher Morsi, Ph.D., P.Ag Environmental Management Officer Operational Policy & Environment Resource Development & Stewardship Branch

Telephone: 250-794-5234 Facsimile: 250-794-5390

E-Mail: Taher.Morsi@bcogc.ca

cc: Margi Meekes, Synergy Environmental Strategies Inc, 9904 106 Street, Fort St John, BC, V1J 1V8



Commission File No. or AD No.:

CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2

Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J 2B0 Phone: (250) 794-5200

Document:

JAN 02 2018

RC Oil and Gas Commission

Date Received

THIS IS AN AUDITABLE DOCUMENT

A

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY

		ADMINIST	RATION		В	
Well Permit No.: 22520	•				_	
Well Name: CNRL KAHNTAH B-016-F/094-H-15			Well Location: B-016-F/094-H-15			
Petroleum Title (Permit, Lease, Number, etc):						
Title Holder(s) (Permittee, Lessee, etc): Canadian Natural Resources Limited						
Surface Landowner: Crown Land			Surface Occupant: N/A			
(Attach Letter of Release) NA Applicant's Agent in Field:)			(Attach Letter of Release)			
Name: Shellie English						
Company: SynergyAspen Environmental Inc.			Position: Reclamation Advisor			
Address: 9904 106 Street		City: Fort St. John		Province: BC		
Postal Code: V1J 1V8	Phone: 250-78		ax: 250-785-1034	Email: senglish@fsjbc.com		
Agent Signature:				Date: November 02, 2017		
× \$1500 Application Fee Attached						
RESTORATION INFORMATION C						
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):						
Wellsite CNRL KAHNTAH B-016-F/049-H-15 was 85 m x 110 m and was constructed on forested, Crown land. Ancillary sites associated with the wellsite include: a winter access road (followed an existing seismic line, with 10 m x 31 m new cut), and a 60 m x 80 m borrow pit, located adjacent to the well location. A common remote sump and common campsite were also proposed with the well location. For the purposes of remediation and reclamation, the common sites are to be associated with well location A-088-C/094-H-15.						
It is in the opintion of SynergyAs no further work is required.	pen Environme	ntal Inc. that CNRL	KAHNTAH B-016-F/094-H	-15 has been satisfacto	rily restored and	
Details of any areas left unrestor	red at Landowne	er's request:				
Crown Land						
					:	
Was "Approval to Construct" sub	ject to any recla	amation conditions?)		☐YES ⊠NO	
Reclamation Inspection Report in	ncluded?				⊠YES □NO	
s this location within the Agricultural Land Reserve? If YES, attach Schedule B						
Updated: 23-June-2016						

Updated: 23-June-2016 Effective: 23-June-2016

APPROVAL - FOR	COMMISSION USE ONLY	E
CERTIFICATE OF RESTORATION	CERTIFICATE NO.	5797
This is to certify that the surface of the land held in conjunctio satisfactorily restored. Despite the issuance of this Certificate	e, the Ministry of Environment ha	
investigation or remedial action upon inspection of the site or restoration requirements for which the Applicant is subsequer		does not relieve the Applicant of any

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act.* Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act.* If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.

Updated: 23-June-2016 Effective: 23-June-2016