

Date: November 30th, 2017

Richlyn Energy Ltd
1103, 600 Princeton Way SW
Calgary, AB T2P 5N4

Attention: Richard Smith

Re: Richlyn Energy Certificate of Restoration Application (Part-II) for the Well Site Richlyn Ladyfern C-45-J/94-H-1 (WA # 22768)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 22767) submitted by Gemini Environmental Solutions Ltd. on behalf of Richlyn Energy Ltd. on November 29th 2017.

The reclamation assessment report reviewed and found that the site has fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5747).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

“The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued.”


And:

“A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site.”

Therefore, Richlyn Energy liability related residual contamination from the subject oil and gas activity remains the responsibility Richlyn Energy Ltd

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

Handwritten signature of Taher Morsi, consisting of a stylized 'T' and 'M'.


Taher Morsi, Ph.D., P.Ag
Environmental Management Officer
Resource Development & Stewardship Branch
Operational Policy & Environment
Telephone: 250-794-5234
Facsimile: 250-794-5390

E-Mail: Taher.Morsi@bcogc.ca

cc: Vanessa James-Davies, Gemini Environmental Solutions Ltd, 10543 100
Street, Fort St John, BC, V1J 3Z4



**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**
Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY				A
Commission File No. or AD No.:		Document:		
ADMINISTRATION				B
Well Permit No.: 22768				
Well Name: Richlyn Lady Fern c-45-J/94-H-01		Well Location: c-45-J/94-H-01		
Petroleum Title (<i>Permit, Lease, Number, etc</i>):				
Title Holder(s) (<i>Permittee, Lessee, etc</i>):				
Surface Landowner: Crown Land <i>(Attach Letter of Release)</i>		Surface Occupant: <i>(Attach Letter of Release)</i>		
Applicant's Agent in Field				
Name: Vanessa James-Davies				
Company: Gemini Corporation		Position Project Manager		
Address: 10543 100 Street		City: Fort St. John		Province: BC
Postal Code: V1J 3Z4	Phone: 250-263-9155	250-263-9156	Email: vjamesdavies@geminiCorp.ca	
Agent Signature: <i>V. James-Davies</i>			Date:	
<input type="checkbox"/> \$1500 Application Fee Attached				

RESTORATION INFORMATION				C
Description of Area(s) Restored (<i>Location, Remote Sump, Access and other disturbed areas affiliated with this location</i>):				
The wellsite and access road were built as per the Survey Plan and were considered fully restored.				
Details of any areas left unrestored at Landowner's request:				
The site was built as surveyed and is located on Crown land. All constructed areas were considered satisfactorily reclaimed. Please refer to the <i>Reclamation Inspection</i> report completed by Gemini Corporation, dated November 21, 2017, for more detail.				
Was "Approval to Construct" subject to any reclamation conditions?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Reclamation Inspection Report included?				<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Is this location within the Agricultural Land Reserve? <i>If YES, attach Schedule B</i>				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

APPROVAL – FOR COMMISSION USE ONLY

D

CERTIFICATE OF RESTORATION


CERTIFICATE NO.

5747

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Nov 30, 2017



Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.