

Date: February 16th, 2018

Canadian Natural Resources Ltd Suite 2500, 855- 2nd Street SW Calgary, AB T2P 4J8

Attention: Ryan Okada, Lead Reclamation

Re: Canadian Natural Resources Certificate of Restoration Application (part II) for the Well Site CNRL Et Al Ring A-65-K/94-H-16 (WA # 23448)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 23448) submitted by SynergyAspen Environmental on behalf of Canadian Natural Resources Limited on January 2nd 2018.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5799).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Canadian Natural Resources Limited remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer

Operational Policy & Environment Resource Development & Stewardship Branch

Telephone: 250-794-5234 Facsimile: 250-794-5390

E-Mail: Taher.Morsi@bcogc.ca


cc: Margi Meekes, Synergy Environmental Strategies Inc, 9904 106 Street, Fort St John, BC, V1J 1V8



CERTIFICATION OF RESTORATION APPLICATION FORM - PART 2

Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J 2B0

Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

A

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY

Commission File No. or AD No.: Document:							
		ADMINI	STR	ATION		В	
Well Permit No.: 23448							
Well Name: CNRL et al RING A-065-K/094-H-16				Well Location: A-065-K/094-H-16			
Petroleum Title (Permit, Lease,	Number, etc):						
Title Holder(s) (Permittee, Lesse	ee, etc): Canadia	an Natural Reso	urce	s Limited			
Surface Landowner: Crown Land (Attach Letter of Release) NA				Surface Occupant: N/A (Attach Letter of Release)			
Applicant's Agent in Field:							
Name: Shellie English							
Company: SynergyAspen Environmental Inc.				Position: Reclamation Advisor			
Address: 9904 106 Street	S Street City: Fort St. John		ohn		Province: BC		
Postal Code: V1J 1V8	Phone: 250-78	35-1030	Fa	x: 250-785-1034	Email: senglish@fsjbc.com		
Agent Signature:				w to	Date: October 25, 2017		
× \$1500 Application Fee Attached							
RESTORATION INFORMATION C							
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):							
Wellsite CNRL et al RING A-065-K/094-H-16 is located on forested Crown land; out of the boundaries of the Agricultural Land Reserve. The wellsite was 90 m x 100 m in size, and was constructed with a clay pad. The ancillary sites tied to the wellsite include: a winter access road (10 m by 1360 m), a borrow pit (80 m by 60 m) and a common remote sump located at c-077-K/94-H-16 (60 m by 60 m). The proposed borrow pit, adjacent to the wellsite as shown on the survey plan, was not constructed.							
It is in the opinion of SynergyAspen Environmental Inc., that the wellsite, access road and ancillary sites have been satisfactorily restored and no further work is required.							
Details of any areas left unrestored at Landowner's request:							
Crown Land							
¥							
Was "Approval to Construct" subject to any reclamation conditions?							
Reclamation Inspection Report included?						⊠YES □NO	
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B						☐YES ⊠NO	
Updated: 23-June-2016							

Effective: 23-June-2016

APPROVAL – FOR	COMMISSION USE ONLY	D	
CERTIFICATE OF RESTORATION	CERTIFICATE NO. 5	5799	
This is to certify that the surface of the land held in conjunctic satisfactorily restored. Despite the issuance of this Certificate investigation or remedial action upon inspection of the site or restoration requirements for which the Applicant is subseque	e, the Ministry of Environment has the author file. Issuance of this certificate does not reli	ity to order further site	
Approval Date: (e) 6 2018	lal	<u> </u>	
	Authorized Commission Employee		

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act.* Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act.* If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.

Updated: 23-June-2016 Effective: 23-June-2016