

Date: April 24th, 2017

Arawn Energy Ltd
O/A BC0769574 BC Ltd
PO Box 336 Stirling, Alberta, Canada
T0K 2E0

Attention: Brian R Sumbot, Consulting Country Manager

Re: Arawn Energy Ltd Certificate of Restoration Application (Part-II) for the Well Site Arawn S Grizzly C-43-B/93-I-15 (WA # 14004) and Arawn S Grizzly C-A43-B/93-I-15 (WA# 23808)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 14004 and WA# 23808 located at the same surface lease) submitted by Adlard Environmental Ltd on behalf of Arawn Energy Ltd on April 13th 2017.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5719).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

“The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued.”


And:

“A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site.”

Therefore potential liability related residual contamination from the subject oil and gas activity remains the responsibility Arawn Energy Ltd

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,



Taher Morsi, Ph.D., P.Ag

Environmental Management Officer
Environmental Management & Reclamation Department
Telephone: 250-794-5234
Facsimile: 250-794-5380
E-Mail: Taher.Morsi@bcogc.ca

cc: Chris Maundrell, Adlard Environmental Ltd, PO Box 293, Charlie Lake, BC, V0C 1H0



CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2
 Physical Address: 6534 Airport Road,
 Fort St. John, B.C. V1J 4M6
 Mailing Address: Bag 2, Fort St. John, B.C.
 V1J 2B0
 Phone: (250) 794-5200

RECEIVED
 APR 13 2017
 Date Received
 BC Oil and Gas Commission
 THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY **A**

Commission File No.: _____ Document: _____

ADMINISTRATION **B**

Well Permit No.: **14004, 23808**

Well Name: ARAWN c-43-B/93-I-15 and c-A43-B/93-I-15 Well Location: c-43-B/93-I-15

Petroleum Title (Permit, Lease, Number, etc): c-43-B/93-I-15

Title Holder(s) (Permittee, Lessee, etc): Arawn Energy

Surface Landowner: Her Majesty the Queen Surface Occupant: Her Majesty the Queen
 (Attach Letter of Release) (Attach Letter of Release)


Applicant's Agent in Field: Brian Sumbot

Name: Brian Sumbot

Company: Arawn Energy O/A BC0769574 BC Ltd Position: Consultant in Country Manager

Address: PO Box 336 City: Stirling Province: Alberta

Postal Code: T0K 2E0 Phone: 403 330 8484 Fax: 888-334-4927 Email: brian.r.sumbot@atlas-canamerica.net

Agent Signature:  Digitally signed by Brian Sumbot
 DN: cn=Brian Sumbot, o=Atlas CanAm, ou, email=brian.r.sumbot@atlas-canamerica.net, c=CA
 Date: 2016.06.27 22:31:15 -06'00' Date: 2016-06-27

\$1500 Application Fee Attached

RESTORATION INFORMATION **C**


Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):

Arawn c-43-B/93-I-15 wellsite, access road, and associated b-34-B/93-I-15 remote sump site

Details of any areas left unrestored at Landowner's request:

N/A

Was "Approval to Construct" subject to any reclamation conditions?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Reclamation Inspection Report included?	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Is this location within the Agricultural Land Reserve? <i>If YES, attach Schedule B</i>	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

APPROVAL – FOR COMMISSION USE ONLY		D
CERTIFICATE OF RESTORATION	CERTIFICATE NO.	<u>5719</u>
<p>This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.</p>		
Approval Date: <u>April 24, 2017</u>		
<i>Authorized Commission Employee</i>		
<p>The personal information requested on this form is collected under the authority of and used for the purpose of administering the <i>Petroleum and Natural Gas Act and the Environmental Management Act</i>. Under certain circumstances, some information may be released subject to the provisions of the <i>Freedom of Information and Protection of Privacy Act</i>. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.</p>		