

Date: February 20th, 2017

TAQA North Ltd 2100, 308-4th Avenue SW Calgary, AB T2P 0H7

Attention: Wes Bell, Northern Environmental Coordinator

Re: <u>TAQA North Certificate of Restoration Application (Part-II) for the Well Site TAQA</u> <u>North Chinchaga B-13-B/94-H-8 (WA # 24958)</u>

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite (<u>Never Drilled</u>) the above referenced well authorization (WA # 24958) submitted by SynergyAspen Environmental on behalf of TAQA North Ltd on December 19th, 2016.

Based upon review of the information provided by the applicant, the reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5699).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Applications & Operations Division Environmental Management and Reclamation Department MAILING 6534 Airport Rd Fort St John BC V1J 4M6

T 250.794-5200 F 250.794-5380 www.bcogc.ca

Therefore TAQA North Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,


Taher Morsi, Ph.D., P.Ag

Environmental Management Officer Applications & Operations Division Environmental Management & Reclamation Department Telephone: 250-794-5234 Facsimile: 250-794-5380 E-Mail: <u>Taher.Morsi@bcogc.ca</u>

cc: Tanya Allen, SynergyAspen Environmental Inc, 9904 106th Street, Fort St John, BC V1J 1V8



CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2 Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J 2B0 Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.					
COMMISSION USE ONLY					
Commission File No.:	Document:				
ADMINISTRATION B					
Well Permit No.: 24958					
Well Name: TAQA NORTH CHINCHAGA B-13-B/94-H-08		Well Location: B-13-B/94	Well Location: B-13-B/94-H-08		
Petroleum Title (Permit, Lease, Number, etc):					
Title Holder(s) (Permittee, Lessee, etc): TAQA	North Ltd.				
Surface Landowner: N/A		Surface Occupant: N/A	Surface Occupant: N/A		
(Atlach Letter of Release)		(Allach Letter of Release)	(Allech Leller of Release)		
Applicant's Agent in Field					
Name: Tanya Allen, P.Ag					
Company: SynergyAspen Environmental		Position: Technical Recl	Position: Technical Reclamation Advisor		
Address: 9904 106 th St. City: Fort St. Joh		John	Province: BC		
Postal Code: V1J 1V8 Phone: 250-	785-1030	Fax: 250-785-1034	Email: tallen@synergyaspen.ca		
Agent Signature: Date: December 10, 2016					
\$1500 Application Fee Attached	. W. W. W.				
	RESTORATIO	INFORMATION		С	
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):					
The wellsite is 80 m x 110 m in size and is lo for access, and no additional access was co will not be linked to the site for any remediati wellsite. The site is located within a forested restored and no further work is required at the	nstructed. A component of reclamation nixed wood area.	mon remote sump and camps purposes. No other ancillary	site were both associated with the site, sites were constructed or affiliated with	but the	
Details of any areas left unrestored at Landov	1949 Dec				

Was "Approval to Construct" subject to any reclamation conditions?	YES NO				
Reclamation Inspection Report included?	YES NO				
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B	YES NO				
	4				
APPROVAL – FOR COMMISSION USE ONLY	D				
CERTIFICATE OF RESTORATION CERTIFICATE NO. 5699					
This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission. Approval Date: Feb Zo, Zo11					
The personal information requested on this form is collected under the authority of and used for the purpose of administering the Per Natural Gas Act and the Environmental Management Act. Under certain circumstances, some information may be released subject the Freedom of Information and Protection of Privacy Act. If you have any questions about the collection, use or disclosure of this in the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.	to the provisions of				