

Date: February 26th, 2018

Whitecap Resources Inc Suite 3800, 525-8th Avenue SW Calgary, AB T2P 1G1

Attention: Amanda Peardon, HSE Advisor

Whitecap Resources Certificate of Restoration Application (part II) for the Well Re: Site Whitecap Et Al Boundary 03-30-86-13 W6M (WA # 02515)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 02515) submitted by SynergyAspen Environmental on behalf of Whitecap Resources Inc. on January 25th, 2018.

The reclamation assessment report reviewed and found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5832).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

6534 Airport Rd

Therefore Whitecap Resources Inc. remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer

Operational Policy & Environment

Resource Development & Stewardship Branch

Telephone: 250-794-5234 Facsimile: 250-794-5390

E-Mail: Taher.Morsi@bcogc.ca

cc: Margi Meekes, Synergy Environmental Strategies Inc, 9904 106 Street, Fort St

John, BC, V1J 1V8



CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2

Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J 2B0

Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

A

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY

ADMINISTRATION B										
Well Permit No.: 02515										
Well Name: Whitecap Boundary 03-30-086-13				Well Location: 03-30-086-13						
Petroleum Title (Permit, Lease, Number, etc): Whitecap Boundary 03-30-086-13										
Title Holder(s) (Permittee, Lessee, etc):										
Surface Landowner: Crown Land				Surface Occupant: NA						
(Attach Letter of Release) NA (Attach Letter of Release) Applicant's Agent in Field: Shellie English (SynergyAspen Environmental Ltd)										
Name: Amanda Peardon										
Company: Whitecap Resources Ltd.				Position: HSE Advisor						
Address: 3800, 525-8 th Avenue Southwest City: Calgary				,	Province: AB					
			Fax	x:403 266 6975	Email: info@wcap.ca					
- 7					Date: December 20,					
X \$1500 Application Fee Attached										
RESTORATION INFORMATION C										
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):										
Wellsite and access road were reclaimed. Topographic and landscape parameters are considered comparable to the adjacent offsite control and compatible with current land-use.										
At the time of the last inspection the site was well vegetated and it was estimated that cover was in excess of 80%. The vegetation										
health, height, and vigour were rated as good during the on-Site assessment. In general large bare patches were not present.										
No noxious or nuisance of weeds of concern were observed at the site.										
Details of any areas left unrestored at Landowner's request:										
Crown Land										
Was "Approval to Construct" subject to any reclamation conditions?							NO			
Reclamation Inspection Report included?						XYES [NO			
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B						☐YES ⊠	NO			

Updated: 23-June-2016 Effective: 23-June-2016

APPROV	/AL — F	OR CO	MMISSI	ON USE (ONLY

CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5832

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Teb 26, 2018

Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act.* Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act.* If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.

Updated: 23-June-2016 Effective: 23-June-2016