

Date: January 20th, 2020

Cenovus Energy Inc.
500 Center Street SE
PO Box 766
Calgary, AB T2P 0M5

Attention: Ole Mrklas, Reclamation Coordinator

Re: Cenovus Energy Certificate of Restoration Application (part II) for the Well Site
CVE Energy Kelly B-28-I/93-P-01 (WA # 4252)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 4252) submitted by Millennium EMS Solutions Ltd on behalf of Cenovus Energy Inc. on December 20th, 2019.

Based upon review of the information provided by the applicant, the reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 6073).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Cenovus Energy Inc. remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

A handwritten signature in dark ink, appearing to read 'Taher Morsi', written over a horizontal line.


Taher Morsi, Ph.D., P.Ag
Environmental Management Officer
Environmental Management & Reclamation Department
Operational Policy & Environment
Telephone: 250-794-5234
Facsimile: 250-794-5390

E-Mail: Taher.Morsi@bcogc.ca

cc: Stacey Ingram, Millennium EMS Solutions Ltd, #106, 10920- 84th Avenue,
Grande Prairie, AB T8X6H2

**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**

Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY**A**

Commission File No. or AD No.:

Document:

ADMINISTRATION**B**Well Permit No.: **04252**Well Name: **CVE ENERGY KELLY B- 028-I/093-P-01**Well Location: **B- 028-I/093-P-01**Petroleum Title (Permit, Lease, Number, etc): **Tenure File # 8005963**Title Holder(s) (Permittee, Lessee, etc): **Cenovus Energy Inc.**Surface Landowner: **N/A – Crown land**
(Attach Letter of Release)Surface Occupant: **N/A**
(Attach Letter of Release)

Applicant's Agent in Field

Name: **Stacey Ingram**Company: **Millennium EMS Solutions Ltd.**Position **Senior Environmental Scientist**Address: **#102, 11312 – 98 Avenue**City: **Grande Prairie**Province: **Alberta**Postal Code: **T8V 8H4**Phone: **(780) 357-5500**Fax: **(780) 357-5501**Email: **singram@mems.ca**Agent Signature: Date: **December 11, 2019**☒ \$1500 Application Fee Attached**RESTORATION INFORMATION****C**

Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):

The wellsite is the only activity associated with the well. The well was drilled in 1977 and abandoned in 2014.

Progressive reclamation was completed at the site and majority of the wellsite has natural encroachment from the surrounding forest species. The well centre area was disturbed for abandonment in 2014 and then remedial activities occurred at the drilling waste disposal area on the wellsite in 2017.

Details of any areas left unrestored at Landowner's request:

Not Applicable

Was "Approval to Construct" subject to any reclamation conditions?

☐ YES ☒ NO

Reclamation Inspection Report included?

☒ YES ☐ NO

Is this location within the Agricultural Land Reserve? If YES, attach Schedule B

☐ YES ☒ NO

APPROVAL – FOR COMMISSION USE ONLY

D

CERTIFICATE OF RESTORATION


CERTIFICATE NO.

6073

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Jun 20, 2020


Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.