



Date: March 27th, 2018

Oil and Gas Commission
Engineering Division
Asset Integrity and Retirement
6534 Airport Road
Fort St John, BC V1J 4M6

Attention: Mike Janzen, Manager, Asset Integrity and Retirement

Re: Oil and Gas Commission Certificate of Restoration Application (Part-II) for the Well Site Orphan E Rigel B-28-K/94-A-09 (WA # 6870) Orphan Site

This office has received an Application for a Certificate of Restoration (CoR-Part II), and Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 6870) submitted by SynergyAspen Environmental Inc. on behalf of Oil and Gas Commission on December 12th 2017.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5865).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore operator remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 261-5710

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi'. The signature is written in a cursive style with a horizontal line above the 'T' and 'a'.

Taher Morsi, Ph.D., P.Ag
Environmental Management Officer
Telephone: 250-794-5234
Facsimile: 250-794-5380

E-Mail: Taher.Morsi@bcogc.ca

cc: Margi Meekes, SynergyAspen Environmental Inc., 9904-106 Street, Fort St John,
BC V1J1V8




**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**
Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200

RECEIVED
DEC 12 2017
BC Oil and Gas Commission
Date Received

THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY		A
Commission File No. or AD No.:	Document:	
ADMINISTRATION		B
Well Permit No.: 06870		
Well Name: Orphan E. Rigel	Well Location: B-028-K/094-A-09	
Petroleum Title (Permit, Lease, Number, etc):		
Title Holder(s) (Permittee, Lessee, etc): Orphan Fund		
Surface Landowner: Crown <i>(Attach Letter of Release)</i>	Surface Occupant: <i>(Attach Letter of Release)</i>	
Applicant's Agent in Field		
Name: Shellie English		
Company: SynergyAspen Environmental Inc.	Position: Project Advisor	
Address: 9904 106 Street	City: Fort St. John	Province: British Columbia
Postal Code: V1J 1V8	Phone: 250-262-5402	Fax: 250-785-1034
Email: senglish@fsjbc.com		
Agent Signature: 	Date: December 7, 2017	
<input type="checkbox"/> \$1500 Application Fee Attached		

RESTORATION INFORMATION		C
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):		
The wellsite was 115 m x 115 m in size and was constructed on forested Crown land. No ancillary sites were associated with the wellsite. The subject wellsite is part of the Orphan Well Fund. It is in the opinion of SynergyAspen that the wellsite has been Satisfactorily restored, and no further work is required at the site.		
Details of any areas left unrestored at Landowner's request:		
N/A		
Was "Approval to Construct" subject to any reclamation conditions? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		
Reclamation Inspection Report included? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		

CERTIFICATE OF RESTORATION


CERTIFICATE NO.

5865

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

March 27, 2018


Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.