

Date: February 21st, 2017

Baytex Energy Trust Suite 2800, 520-3rd Ave SW Calgary, AB T2P 0R3

Attention: Anthony Traverse

Re: <u>Baytex Energy Certificate of Restoration Application (Part-II) for the Well Site</u> Baytex Et Al W Flatrock 16-27-84-17 W6M (WA # 7531)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report (Schedule B) for the wellsite for the above referenced well authorization (WA # 7531) submitted by Highmark Environmental Services Ltd on behalf of Baytex Energy Ltd on December 6th, 2016.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5702).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Baytex Energy Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer

Telephone: 250-794-5234 Facsimile: 250-794-5380

E-Mail: Taher.Morsi@bcogc.ca


cc: Chris Weissbach, Highmark Environmental Services Ltd, 10121-95th Avenue, St.

John, BC, V1J 1H9



CERTIFICATION OF RESTORATION APPLICATION FORM - PART 2

Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J2B0 Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature. **COMMISSION USE ONLY** Α Commission File No. or AD No.: Document: **ADMINISTRATION** В Well Permit No.: WA 7531 Well Name: Baytex Et Al Flatrock Well Location: 16-27-084-17W6M Petroleum Title (Permit, Lease, Number, etc): Title Holder(s) (Permittee, Lessee, etc): Baytex Energy Ltd. Surface Landowner: John & Alan Bidulka Surface Occupant: (Attach Letter of Release) Please see section 6.4 of Schedule B report. (Attach Letter of Release) Applicant's Agent in Field Name: Chris Weissbach Company: Highmark Environmental Position: Senior Project Manager Address: 10121-95th avenue City: Fort St. John Province: British Columbia Phone:250-261-6994 Fax: 250-261-6928 Postal Code: V1J 1H9 Email:chrisw@hesl.ca Date: November 7, 2016 Agent Signature: ■ \$1500 Application Fee Attached RESTORATION INFORMATION C Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location): Well site as well as lease road.

Updated: 23-June-2016 Effective: 23-June-2016

All areas fully restored.

Details of any areas left unrestored at Landowner's request:

Was "Approval to Construct" subject to any reclamation con	ditions?		YES N
Reclamation Inspection Report included?			YES N
Is this location within the Agricultural Land Reserve? If YES	, attach Schedule B		YES NO
APPROVAL – FOR (COMMISSION USE ONLY		D
CERTIFICATE OF RESTORATION	CERTIFICATE NO.	5702	
This is to certify that the surface of the land held in conjunction satisfactorily restored. Despite the issuance of this Certificate investigation of remedial action upon inspection of the site or frestoration requirements for which the Applicant is subsequen Approval Date:	, the Ministry of Environment ha file. Issuance of this certificate o	s the authority to order full loes not relieve the Applica	her site
·	Authorized Commission	Employee	`
The personal information requested on this form is collected under the Natural Gas Act and the Environmental Management Act. Under certa the Freedom of Information and Protection of Privacy Act. If you have the Corporate Services Branch, Records Administrator, in Fort St. Joh	in circumstances, some information any questions about the collection,	may be released subject to the	ne provisions of

Updated: 23-June-2016 Effective: 23-June-2016