

Date: November 30th, 2017

Pengrowth Energy Corporation
2100, 222 3rd Avenue SW
Calgary, AB
T2P0B4

Attention: Darren DuPerrier

Re: Pengrowth Corporation Certificate of Restoration Application (Part-II) for the Well Site Pengrowth Weasel B-B42-B/94-H-2 (WA # 8091)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 8091) submitted by SNC-Lavalin Environment on behalf of Pengrowth Energy Corporation on November 23rd, 2017.

Based upon review of the information provided by the applicant, the reclamation inspection report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5748).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore potential liability related residual contamination from the subject oil and gas activity on site remains the responsibility Pengrowth Energy Corporation

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi', with a horizontal line drawn underneath the name.

Taher Morsi, Ph.D., P.Ag
Environmental Management Officer
Resource Development & Stewardship Branch
Operational Policy & Environment
Telephone: 250-794-5234
Facsimile: 250-794-5390

E-Mail: Taher.Morsi@bcogc.ca

cc: Kathleen Juneau, SNC-Lavalin Environmental & Water Inc, #202- 10012 97th
Avenue, Fort St John V1J 5P3

**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**

Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200

RECEIVED
NOV 23 2017
BC Oil and Gas Commission

Date Received

THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY**A**

Commission File No. or AD No.:

Document:

ADMINISTRATION**B**

Well Permit No.: 08091

Well Name: PENGROWTH WEASEL B-B042-B/094-H-02

Well Location: B-B42-B/94-H-2

Petroleum Title (Permit, Lease, Number, etc): N/A

Title Holder(s) (Permittee, Lessee, etc): Pengrowth Energy Corporation

Surface Landowner: Crown

Surface Occupant: N/A

(Attach Letter of Release)

(Attach Letter of Release)

Applicant's Agent in Field: Alana Ross, C.Tech - Reclamation Specialist

Name: Darren DuPerrier

Company: Pengrowth Energy Corporation

Position: Environmental Advisor

Address: 2100, 222 3rd Ave SW

City: Calgary

Province: Alberta

Postal Code: T2P 0B4

Phone: 403 269 5036

Fax:

Email: Darren.DuPerrier@Pengrowth.com

Agent Signature:

Date: 2017-11-22

☒ \$1500 Application Fee Attached**RESTORATION INFORMATION****C**

Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):

The site and associated temporary access road and campsite are located on Crown land. The site's status is "Abandoned".

The site is now suitable for a Certificate of Restoration Part 2 Approval.

Details of any areas left unrestored at Landowner's request:

N/A

Was "Approval to Construct" subject to any reclamation conditions?


☐ YES ☒ NO

Reclamation Inspection Report included?

☒ YES ☐ NO

Is this location within the Agricultural Land Reserve? If YES, attach Schedule B

☐ YES ☒ NO

APPROVAL – FOR COMMISSION USE ONLY		D
CERTIFICATE OF RESTORATION	CERTIFICATE NO.	<u>5748</u>
<p>This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.</p>		
Approval Date:	<u>NOV 30th, 2017</u>	 Authorized Commission Employee
<p>The personal information requested on this form is collected under the authority of and used for the purpose of administering the <i>Petroleum and Natural Gas Act</i> and the <i>Environmental Management Act</i>. Under certain circumstances, some information may be released subject to the provisions of the <i>Freedom of Information and Protection of Privacy Act</i>. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.</p>		