



Date: December 6th, 2016

Advantage Oil & Gas Ltd
300, 400-2nd Ave SW
Calgary, AB T2P 5E9

Attention: Reg Beck

Re: Advantage Oil and Gas Certificate of Restoration Application (Part-II) for the Well Site Advantage Martin D-27-H//94-H-5 (WA # 9010)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 9010) submitted by Ecoventure Inc on behalf of Advantage Oil & Gas Ltd December 1st, 2016.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5645).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore potential liability related residual contamination from the subject oil and gas activity remains the responsibility Advantage Oil & Gas Ltd.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi', with a horizontal line drawn underneath.


Taher Morsi, Ph.D., P.Ag
Environmental Management Officer
Telephone: 250-794-5234
Facsimile: 250-794-5380

E-Mail: Taher.Morsi@bcogc.ca

cc: Chris Newton, Ecoventure Inc , Suite 301, 10509-81 Ave NW, Edmonton, AB
T6E 1X7


**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**

Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY			A
Commission File No.:		Document:	
ADMINISTRATION			B
Well Permit No.: 09010			
Well Name: Advantage Martin D-027-H/094-H-05		Well Location: D-27-H/94-H-05	
Petroleum Title (Permit, Lease, Number, etc):			
Title Holder(s) (Permittee, Lessee, etc): Advantage Oil and Gas Ltd.			
Surface Landowner: Crown (Attach Letter of Release)		Surface Occupant: (Attach Letter of Release)	
Applicant's Agent in Field			
Name: Carlos Arregoces			
Company: Ecoventure Inc.		Position: Senior Manager	
Address: 115-18 Royal Vista Link NW		City: Calgary	Province: Alberta
Postal Code: T3R 0K4	Phone: 403-265-2498 ext. 202	Fax: 403-265-2740	Email: carlos.arregoces@ecoventure.ca
Agent Signature: 			Date: November 29, 2016
<input checked="" type="checkbox"/> \$1500 Application Fee Attached			

RESTORATION INFORMATION		C
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):		
The areas that have been restored on the D-027-H/094-H-05 Well site (122 m x 122 m), temporary trailer site (10 m x 60m) and temporary campsite (30 m x 60 m) are consistent with the desired outcome and vegetation on the site which is meeting the trajectory of the off-site forest community. Access to the site was via an existing winter access trail which is densely vegetated with an excellent tree and shrub cover.		
Details of any areas left unrestored at Landowner's request:		
All areas have been restored.		
Was "Approval to Construct" subject to any reclamation conditions? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		
Reclamation Inspection Report included? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		

Updated: 20 January 2014
Effective: 6 February 2014

APPROVAL - FOR COMMISSION USE ONLY

D


CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5645

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Dec 6th, 2016
Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.