

Date October 24th, 2017

Paramount Resources Ltd 4700 Bankers Hall West 888 3<sup>rd</sup> Street SW Calgary, AB T2P 5C5

Attention: Larry Yoon

Re: <u>Paramount Resources Certificate of Restoration Application (Part-II) for the Well</u> PARA Drake C-93-C/94-H-01 (WA # 9076)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 9076) submitted by North Shore Environmental Consultants on behalf of Paramount Resources Ltd on April 19 2016. On September 19<sup>th</sup> 2017, we received CoR (part-I) application with associated documents.

The operator be aware that there is CNRL Drake C-A93-C/94-H-1 (WA# 15534) active wellsite overlaps with WA# 9076. The CNRL will be responsible for all reclamation activities associated with the wellsite and its associated facilities based on an agreement letter.

The reclamation assessment report was reviewed and found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5739).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Paramount Resources Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-234

Sincerely,

Taher Morsi, Ph.D., P.Ag Environmental Management Officer

Operational Policy & Environment

Resource Development & Stewardship Branch

Telephone: 250-794-5234 Facsimile: 250-794-5380

E-Mail: Taher.Morsi@bcogc.ca


cc: Brent Walchuk, North Shore Environmental Consultants Inc, #143, 201 Kaska

Road, Sherwood Park, AB T8A 2J6



## CERTIFICATION OF RESTORATION APPLICATION FORM - PART 2

Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J 2B0 Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY					A
Commission File No.: Document:					
ADMINISTRATION B					
Well Permit No.: 09076					
Well Name: PARA DRAKE C-093-C/094-H-01	Well Location:200/C-093-	Well Location:200/C-093-C/094-H-01			
Petroleum Title (Permit, Lease, Number, etc): N/A					
Title Holder(s) (Permittee, Lessee, etc): Paramount Resources Ltd.					
Surface Landowner: Crown Land (Attach Letter of Release)		Surface Occupant: N/A (Attach Letter of Release)			
Applicant's Agent in Field					
Name: Brent Walchuk, B.Sc., P.Ag.					
Company: North Shore Environmental Consultants Inc.		Position Remediation/Red	clamation Supervisor		
Address: #143, 201 Kaska Road City: Sherwood Pa		Park	Province: Alberta		
Postal Code: T8A 2J6 Phone: (780)	167-3354	Fax: (780) 464-9622	Email:bwalchuk@northshoreenv.com		m
Agent Signature:		Date: April 13, 2016			
✓ \$1500 Application Fee Attached					
RESTORATION INFORMATION C					С
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):					
The Paramount 200 wellsite is overlapped by the producing CNRL 202 wellsite. CNRL has assumed responsibility for all reclamation					
activities on the wellsite and its associated facilities. A letter stating this from CNRL is included in the Reclamation Inspection report.					
The associated facilities include the access road (existing), campsite (existing), trailer site, borrow pit, and remote sump.					
Details of any areas left unrestored at Landowner's request:					
The wellsite and its associated facilities are being actively used by the CNRL 202/C-093-C/094-H-01 well.					
Was "Approval to Construct" subject to any reclamation conditions?					NO
Reclamation Inspection Report included?				⊠YES [	NO
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B				YES X	ИО

Updated: 20 January 2014 Effective: 6 February 2014

## APPROVAL - FOR COMMISSION USE ONLY

ח

CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5739

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date: OCT 24, 2017

Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act.* Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act.* If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.

Updated: 20 January 2014 Effective: 6 February 2014