

#### GENERAL ORDER - 2021-0054-02

Section 49 Oil and Gas Activities Act

### **Issued to:**

Erikson National Energy Inc. Suite 1900,717-7th Ave, SW Calgary, Alberta, T2P 0Z3

Attention: Mr. Dan Jalbert

### **Order:**

Pursuant to section 49(1)(d) and (e) of the *Oil and Gas Activities Act* (the Act), I, Andy Johnson, order that Erikson National Energy Inc. (Erikson) must:

- 1. On or before May 15, 2022, begin operations to remove a volume of liquid from the total capacity of frac water storage site located at d-024-G/094-P-10 (the "Site") to a minimum level of 1 metre below freeboard, to be completed no later than June 30, 2022.
- 2. On May 22, 2022, and at intervals of every 7 days thereafter until June 30, 2022, provide a weekly report of the current freeboard measurement electronically to C&E@bcogc.ca.
- 3. On July 1, 2022, and the 1<sup>st</sup> day of each month thereafter until all liquid is emptied from the Site, submit a monthly report of the current freeboard measurement electronically to C&E@bcogc.ca.
- 4. On or before May 15, 2022, submit the required annual summary of monthly field monitoring and the annual laboratory analysis electronically to <a href="mailto:C&E@bcogc.ca">C&E@bcogc.ca</a>.

## **Conditions:**

A. This order shall remain in effect until amended or terminated in whole or in part by the Commission.

## **Reasons:**

I make this Order for the following reasons:

- i. Erikson is the holder of an authorization issued under the Land Act for the purpose of constructing and operating the Site (the "Permit") which was transferred to them in 2020.
- ii. Condition 1(f) of the Permit requires that at least 1 metre of freeboard be maintained at all times to prevent overflow.
- iii. Condition 1(j) of the Permit requires submission of an annual summary of monthly field monitoring and the annual laboratory analysis to the Commission.
- iv. Previous annual summary reports have shown indication of a potential leak at the Site liner.
- v. To date Erikson has not submitted to the Commission an annual summary of field monitoring and laboratory analysis as required by Permit condition 1(j).
- vi. Records received by the Commission from Erikson indicate that the Site freeboard measured 1.016m on September 17, 2021.
- vii. In March 2022, Commission staff noted a significant volume of snow covering the Site.
- viii. I am of the opinion that Erikson has failed to comply with condition 1(j) of the Permit.
- ix. I am of the opinion that this order is necessary to protect the environment.

# **Review and Appeal:**

Erikson may request a review of this order under section 70 of the Act by submitting a request for review to ogc.determinationreviews@bcogc.ca

Alternatively, Erikson may appeal this Order to the Oil and Gas Appeal Tribunal under section 72 of the Act. The process for appeals may be found at www.ogat.gov.bc.ca and a notice of appeal may be sent to the Oil and Gas Appeal Tribunal at:

Oil and Gas Appeal Tribunal PO Box 9425 Stn Prov Govt Victoria, BC, V8W 9V1

Andy Johnson

Vice President, Operations Oil and Gas Commission

DATED AT Fort St. John, in the Province of British Columbia, this 29 day of April, 2022